



WARPING MILL




Step 1




X4

Step 2




X2


Step 3




Step 4



Step 5




Step 6




Bearing is underneath


Step 7





Step 8



Step 9



Step 10



*Optional accessory Ashford Spinning Wheel Oil

